

Vacuum Products Division

CE

Capacitance Diaphragm Gauge

CDG-500

Operating Instructions

Manual No. TQNa76e1 Revision 5 May 2012

CDG-500



Copyright 2012 Agilent, Inc.

Declaration of Conformity KonformiÄtserkkirung Declaration de Conformité Declaration de Conformité Declaration de Conformité Dichiarazione di Conformità 一致性声明 通合冗言 적학성 신인	Agilent Technologies
We Wir Nous Nosotros Wii Riii Riii Rii: ち 우리는	Agilent Technologies 121 Hartwell Ave. Lexington, MA 02421-3133 USA
declare under our sole responsibilit erklären, in allenninger Verantwortut déclarons sous notre seule responsa declaranso, bajo nuestra sola respo verklaren onder onze verantwoorde dichiariamo sotto nostra unica resp 基子独立承担责任的原则, 하声明 试, 哲比和论办责任の下、この宣言: 당사의 책임하여	ng, daß dieses Produkt, bilité que le produit, nsabilidad, que el producto, lijkheid, dat het product, onsabilità, che il prodotto,
Ca	pacitance Diaphragm Gauge CDG-500
auf das sich diese Erklärung bezieht, auquel se réfère cette déclaration est al que se réfère cette déclaration est waamaar deze verklaring verwijst, aa a cui se rifersce questa dichiarazione 符合以下标准或其它标准之档要求。 が,以下の規格またはその他の基準書	conformity with the following standard(s) or other normative documents. mit der/den flogenden Norm(en) oder Richtlinie(n) übereinstimmt. conforme ba (aug) norme(s) ou au(s) documento(s) normatif(s). onforme a la(s) norma(s) u otu(s) documento(s) normativo(s). n de volende norm(en) of richtlijn(en) beantwoodt. è conforme allay sequente[N norma/c documento[N normativo]. be conforme allay sequente[N norma/c documento] normativo]. braica@o+oことを宣言します。 h 기타 표준 문서를 준수한다는 것을 선언합니다.
 EN 61000 6 2:2005 (EN 	IC: generic immunity standard)
 EN 61000 6 3:2007 (EN 	IC: generic emission standard)
 EN 61010 1:2001 (Safet laboratory use) 	ty requirements for electrical equipment for measurement, control and
 EN 61326:1997 + A1:199 	88 + A2:2001 +A3:2003 (EMC require-ments for electrical equipment for
measurement, control and labor	atory use)
	in Ehmann erations Manger

Operations Manger Aglent, Inc. Vacuum products Division Lexington, MA USA


Contents

Product Identification Validity Intended Use, Function Trademark, Patents Scope of Delivery	6 7 9 9
1 Safety 1.1 Symbols Used 1.2 Personnel Qualifications 1.3 General Safety Instructions 1.4 Liability and Warranty	11 11 12 12
2 Technical Data	13
3 Installation 3.1 Vacuum Connection 3.2 Power Connection	18 18 21
 4 Operation 4.1 Displays 4.2 Zeroing the Gauge 4.3 Switching Functions 4.4 Activating the Factory Setting (Factory Reset) 	23 23 24 28 31
5 Deinstallation	32
6 Maintenance, Repair	34
7 Returning the Product	34
8 Disposal	35
Further Information	36
ETL Certification	37

For cross-references within this document, the symbol ($\rightarrow \boxtimes XY$) is used, for cross-references to further documents, listed under "Further Information", the symbol ($\rightarrow \square [Z]$).

Product Identification

In all communications with Agilent, please specify the information given on the product nameplate. For convenient reference copy that information into the space provided below.



Validity

This document applies to products with the following part numbers:

Gauges without switching functions

		Measurem	ent range, Full S	Scale (F.S.)
Part number	Flange	Torr	Pascal	mbar
CDG500T1000KF16	DN 16 ISO-KF	10 ⁻¹	1.33×10 ¹	1.33×10 ⁻¹
CDG500T1000VCR8	8 VCR [®]	 1000 (F.S.)	 133'322 (F.S.)	 1333 (F.S.)
CDG500T0100KF16	DN 16 ISO-KF	10 ⁻²	1.33×10 ⁰	1.33×10 ⁻²
CDG500T0100VCR8	8 VCR [®]	 100 (F.S.)	 13'332.2 (F.S.)	 133 (F.S.)
CDG500T0010KF16	DN 16 ISO-KF	10 ⁻³	1.33×10 ⁻¹	1.33×10 ⁻³
CDG500T0010VCR8	8 VCR [®]	 10 (F.S.)	 1'333.22 (F.S.)	 13.3 (F.S.)
CDG500T0001KF16	DN 16 ISO-KF	10 ⁻⁴	1.33×10 ⁻²	1.33×10 ⁻⁴
CDG500T0001VCR8	8 VCR [®]	 1 (F.S.)	 133.322 (F.S.)	 1.3 (F.S.)

		Measurem	ent range, Full S	Scale (F.S.)
Part number	Flange	Torr	Pascal	mbar
CDG500T1000KF16S	DN 16 ISO-KF	10 ⁻¹	1.33×10 ¹	1.33×10 ⁻¹
CDG500T1000VCR8S	8 VCR [®]	 1000 (F.S.)	 133'322 (F.S.)	 1333 (F.S.)
CDG500T0100KF16S	DN 16 ISO-KF	10 ⁻²	1.33×10 ⁰	1.33×10 ⁻²
CDG500T0100VCR8S	8 VCR [®]	 100 (F.S.)	 13'332.2 (F.S.)	 133 (F.S.)
CDG500T0010KF16S	DN 16 ISO-KF	10 ⁻³	1.33×10 ⁻¹	1.33×10 ⁻³
CDG500T0010VCR8S	8 VCR [®]	 10 (F.S.)	 1'333.22 (F.S.)	 13.3 (F.S.)
CDG500T0001KF16S	DN 16 ISO-KF	10 ⁻⁴	1.33×10 ⁻²	1.33×10 ⁻⁴
CDG500T0001VCR8S	8 VCR [®]	 1 (F.S.)	 133.322 (F.S.)	 1.3 (F.S.)

Gauges with two switching functions

The part number (PN) can be taken from the product nameplate.

If not indicated otherwise in the legends, the illustrations in this document correspond to CDG-500 gauges with the DN 16 ISO-KF vacuum connection. They apply to the gauges with other vacuum connection by analogy.

We reserve the right to make technical changes without prior notice.

All dimensions in mm.

Intended Use

The Capacitance Diaphragm Gauge CDG-500 is intended for absolute pressure measurement of gases in its respective pressure range ($\rightarrow \mathbb{B}$ 7).

The gauge can be operated in connection with an Agilent AGC-100 Vacuum Gauge Controller, an Agilent Turbo AG Rack Controller, or with another appropriate measuring unit.

Function

The Capacitance Diaphragm Gauge consists of a capacitive sensor element made of aluminum oxide ceramics and electronics which convert the capacitance into a DC voltage output signal. The output signal is linear to the measured pressure and independent of the gas type.

Trademark

VCR[®] Swagelok Marketing Co.

Patents

EP 1070239 B1, 1040333 B1 US Patents 6528008, 6591687, 7107855, 7140085

Scope of Delivery

- 1× gauge
- 1x pin for adjusting settings via buttons
- 1x Calibration Test Report
- 1x Operating Manual

Contents

Val Inte Tra	duct Identification idity ended Use, Function demark, Patents ope of Delivery	6 7 9 9 9
1.2 1.3	Safety Symbols Used Personnel Qualifications General Safety Instructions Liability and Warranty	11 11 11 12 12
2	Technical Data	13
3 3.1 3.2	Installation Vacuum Connection Power Connection	18 18 21
4.3	Operation Displays Zeroing the Gauge Switching Functions Activating the Factory Setting	23 23 24 28 (Factory Reset) 31
5	Deinstallation	32
6	Maintenance, Repair	34
7	Returning the Product	34
8	Disposal	35
Fur	ther Information	36
ETI	L Certification	37
EC	Declaration of Conformity	Error! Bookmark not defined.

For cross-references within this document, the symbol ($\rightarrow \mathbb{B} XY$) is used, for cross-references to further documents, listed under "Further Information", the symbol ($\rightarrow \square [Z]$).

1 Safety

1.1 Symbols Used

\frown	
STOP	DANGER
\sim	

Information on preventing any kind of physical injury.

WARNING


Information on preventing extensive equipment and environmental damage.



Information on correct handling or use. Disregard can lead to malfunctions or minor equipment damage.



1.2 Personnel Qualifications



All work described in this document may only be carried out by persons who have suitable technical training and the necessary experience or who have been instructed by the end-user of the product.

1.3 General Safety Instructions

- Adhere to the applicable regulations and take the necessary precautions for the process media used.
 Consider possible reactions with the product materials.
- Adhere to the applicable regulations and take the necessary precautions for all work you are going to do and consider the safety instructions in this document.
- Before beginning to work, find out whether any vacuum components are contaminated. Adhere to the relevant regulations and take the necessary precautions when handling contaminated parts.

Communicate the safety instructions to all other users.

1.4 Liability and Warranty

Agilent assumes no liability and the warranty becomes null and void if the end-user or third parties

- disregard the information in this document
- · use the product in a non-conforming manner
- make any kind of interventions (modifications, alterations etc.) on the product
- use the product with accessories not listed in the product documentation.

The end-user assumes the responsibility in conjunction with the process media used.

Gauge failures due to contamination or wear and tear are not covered by the warranty.

2 Technical Data

Measurement range	\rightarrow "Validity"
Accuracy 1)	0.20% of reading
Temperature effect on zero ≥10 Torr/mbar (F.S.) 1 Torr/mbar (F.S.)	0.0050% F.S./ °C 0.015% F.S./ °C
Temperature effect on span	0.01% of reading / °C
Resolution	0.003% F.S.
Gas type dependence	none
Output signal analog (measuring signal)	
Voltage range	–5 … +10.24 V
Measuring range	0 +10 V
Relationship voltage-pressure	linear
Output impedance	$0 \ \Omega$ (short-circuit proof)
Loaded impedance	>10 kΩ
Response time	30 ms
Gauge identification	Resistance 13.2 k Ω referenced to supply common (voltage at pin 10 \leq 5 V)

¹⁾ Non-linearity, hysteresis, repeatability in the calibrated range at 25 °C ambient operating temperature without temperature effects after operation of 2 h.

Switching functions	SP1, SP2
Setting range	0 +10 V
Hysteresis	1% F.S.
Relay contact	30 VDC / ≤0.5 ADC floating (n.o.)
closed	at low pressure (LED is lit)
open	at high pressure (LED is dark)
Switching time	≤50 ms
RS232C interface	
Transmission rate	9600 baud
Data format	binary
	8 data bits
	one stop bit

Connection

no handshake → "Electrical Connection"

no parity bit

Further information about the RS232C interface $\rightarrow \square$ [2].

Supply



STOP DANGER

The gauge may only be connected to power supplies, instruments or control devices that conform to the requirements of a grounded protective extralow voltage (SELV) and limited power source (LPS), Class 2. The connection to the gauge has to be fused ²⁾.

Supply voltage at the gauge

ripple


+14 ... +30 VDC Class 2 / LPS ≤1 V_{pp}

²⁾ Agilent controllers fulfill this requirement.

Current consumption	<500 mA
	(max. starting current)
Power consumption	
(depending on supply voltage)	≤1 W
Fuse required ²⁾	1 AT (slow), automatic reset (Polyfuse)
The gauge is protected against revevoltage.	erse polarity of the supply
Electrical connection	15-pin D-Sub, male
Sensor cable	
without switching functions	5-pin plus shielding
with switching functions	9-pin plus shielding
Cable length	≤100 m (0.14 mm ² conductor)
	areas sections are required
For longer cables, larger conductor $(R_{cable} \leq 1.0 \Omega)$.	cross-sections are required
a	
(R _{cable} ≤1.0 Ω).	→ "Power Connection"
$(R_{cable} \leq 1.0 \Omega).$ Grounding concept	
(R _{cable} ≤1.0 Ω). Grounding concept Vacuum flange - signal common	→ "Power Connection"
(R _{cable} ≤1.0 Ω). Grounding concept Vacuum flange - signal common	→ "Power Connection" conducted separately; for dif-
(R _{cable} ≤1.0 Ω). Grounding concept Vacuum flange - signal common Supply common - signal common	→ "Power Connection" conducted separately; for dif-
(R _{cable} ≤1.0 Ω). Grounding concept Vacuum flange - signal common Supply common - signal common Materials exposed to vacuum	\rightarrow "Power Connection" conducted separately; for differential measurement (10 Ω)
(R _{cable} ≤1.0 Ω). Grounding concept Vacuum flange - signal common Supply common - signal common Materials exposed to vacuum Flange, tube	→ "Power Connection" conducted separately; for dif- ferential measurement (10Ω) stainless steel AISI 316L
(R _{cable} ≤1.0 Ω). Grounding concept Vacuum flange - signal common Supply common - signal common Materials exposed to vacuum Flange, tube Sensor and diaphragm	→ "Power Connection" conducted separately; for dif- ferential measurement (10Ω) stainless steel AISI 316L ceramics ($AI_2O_3 \ge 99.5\%$) glass ceramics solder
(R _{cable} ≤1.0 Ω). Grounding concept Vacuum flange - signal common Supply common - signal common Materials exposed to vacuum Flange, tube Sensor and diaphragm Sensor–diaphragm connection	→ "Power Connection" conducted separately; for dif- ferential measurement (10Ω) stainless steel AISI 316L ceramics ($AI_2O_3 \ge 99.5\%$) glass ceramics solder AgTiCu hard solder, Vacon 70
(R _{cable} ≤1.0 Ω). Grounding concept Vacuum flange - signal common Supply common - signal common Materials exposed to vacuum Flange, tube Sensor and diaphragm Sensor–diaphragm connection Ceramics–metal connection	→ "Power Connection" conducted separately; for dif- ferential measurement (10Ω) stainless steel AISI 316L ceramics ($Al_2O_3 \ge 99.5\%$) glass ceramics solder AgTiCu hard solder, Vacon 70 (28% Ni, 23% Co, 49% Fe)
(R _{cable} ≤1.0 Ω). Grounding concept Vacuum flange - signal common Supply common - signal common Materials exposed to vacuum Flange, tube Sensor and diaphragm Sensor–diaphragm connection Ceramics–metal connection Internal volume Admissible pressure (absolute) 1000 Torr/mbar (F.S.)	→ "Power Connection" conducted separately; for dif- ferential measurement (10Ω) stainless steel AISI 316L ceramics ($Al_2O_3 \ge 99.5\%$) glass ceramics solder AgTiCu hard solder, Vacon 70 (28% Ni, 23% Co, 49% Fe)
(R _{cable} ≤1.0 Ω). Grounding concept Vacuum flange - signal common Supply common - signal common Materials exposed to vacuum Flange, tube Sensor and diaphragm Sensor–diaphragm connection Ceramics–metal connection Internal volume Admissible pressure (absolute)	→ "Power Connection" conducted separately; for dif- ferential measurement (10Ω) stainless steel AISI 316L ceramics ($Al_2O_3 \ge 99.5\%$) glass ceramics solder AgTiCu hard solder, Vacon 70 (28% Ni, 23% Co, 49% Fe) ≤3.6 cm ³


Admissible temperatures	
Storage Operation Bakeout (not in operation)	-40 °C +65 °C +5 °C +50 °C ≤110 °C at the flange
Relative humidity	≤80% at temperatures ≤+31 °C decreasing to 50% at +40°C
Use	indoors only, altitude up to 2000 m NN
Degree of protection	IP 30

Dimensions [mm]



Weight

≤370 g



Analog Measuring Signal vs. Pressure



	Torr	mbar 3)	Pa 3)
с	1.00	1013.25 / 760 = 1.3332	101325 / 760 = 133.3224

Example: Gauge with 10 Torr F.S. Measuring signal $U_{out} = 6 V$

³⁾ Source: NPL (National Physical Laboratory) Guide to the Measurement of Pressure and Vacuum, ISBN 0904457x / 1998

3 Installation

WARNING: fragile components

The ceramic sensor may be damaged by impacts. Do not drop the product and prevent shocks and impacts.

3.1 Vacuum Connection

OP DANGER

DANGER: overpressure in the vacuum system >1 bar

Injury caused by released parts and harm caused by escaping process gases can result if clamps are opened while the vacuum system is pressurized.

Do not open any clamps while the vacuum system is pressurized. Use the type clamps which are suited to overpressure.

STOP DANGER
DANGER: overpressure in the vacuum system >2.5 bar KF flange connections with elastomer seals (e.g. O-rings) cannot withstand such pressures. Process media can thus leak and possibly damage your health. Use O-rings provided with an outer centering ring.

STOP DANGER



DANGER: protective ground

Products that are not correctly connected to ground can be extremely hazardous in the event of a fault.

Electrically connect the gauge to the grounded vacuum chamber. This connection must conform to the requirements of a protective connection according to EN 61010:

- · VCR flanges fulfill this requirement.
- For gauges with a KF flange, use a conductive metallic clamping ring.

<u>/!</u>

Caution

Caution: vacuum component

Dirt and damages impair the function of the vacuum component.

When handling vacuum components, take appropriate measures to ensure cleanliness and prevent damages.

Caution


Caution: dirt sensitive area

Touching the product or parts thereof with bare hands increases the desorption rate.

Always wear clean, lint-free gloves and use clean tools when working in this area.

Mount the gauge so that no vibrations occur. The gauge may be mounted in any orientation. To keep condensates and particles from getting into the measuring chamber preferably choose a horizontal to upright position and possibly use a seal with a centering ring and filter. If adjustment should be possible after the gauge has been installed, be sure to install it so that the buttons can be accessed with a pin ($\rightarrow \mathbb{R}$ 24).

Remove the protective lid and connect the product to the vacuum system.



3.2 Power Connection

P	Make sure the vacuum connection is properly made
	(→ 🖹 18).

STOP DANGER
The gauge may only be connected to power supplies, instruments or control devices that conform to the requirements of a grounded protective extra- low voltage (SELV) and limited power source (LPS), Class 2. The connection to the gauge has to be fused $^{4)}$.




Ground loops, differences of potential, or EMC problems may affect the measurement signal. For optimum signal quality, please do observe the following notes:

- Connect the cable shield to ground on one side via the chassis ground. Do not connect the other side of the shield
- Connect the supply common with protective ground directly at the power supply.
- Use differential measurement input (signal common and supply common conducted separately).
- Potential difference between supply common and housing ≤18 V (overvoltage protection).


⁴⁾ VARIAN controllers fulfill this requirement.



If no sensor cable is available, make one according to the following diagram.



- Pin 15 Housing (Chassis Ground)
- case Connector case





Onnect the sensor cable to the gauge and secure it using the lock screws.



Connect the sensor cable to the controller.

4 Operation

Put the gauge into operation. If you are using an Agilent controller, define the measurement range ($\rightarrow \square$ [1]).

A warm-up time of at least ¼ hour should be allowed; for exact pressure measurements a warm-up time of at least 2 hours is required.

4.1 Displays



State	Meaning
lit	Measurement mode
flashing	Other mode, error, out of measurement range
lit	p ≤ setpoint level 1
flashing	Adjusting setpoint <1>
lit	p ≤ setpoint level 2
flashing	Adjusting setpoint <2>
	lit flashing lit flashing lit

^{*)} Gauges with switching functions only.

4.2 Zeroing the Gauge

The gauge is factory calibrated while "standing upright" $(\rightarrow$ "Calibration Test Report").



We recommend performing a zero adjustment, when the gauge is operated for the first time.

Due to long time operation or contamination, a zero drift could occur and zero adjustment may become necessary.

For adjusting the zero, operate the gauge under the same constant ambient conditions and in the same mounting orientation as normally.

The output signal (measuring signal) is depending on the mounting orientation. The signal difference between the vertical and horizontal mounting orientation is:

F.S.	∆U / 90°
1000 Torr/mbar	≈2 mV
100 Torr/mbar	≈10 mV
10 Torr/mbar	≈50 mV
1 Torr/mbar	≈300 mV



If the gauge is operated via a controller, the zero of the whole measuring system has to be adjusted on the controller: first, adjust the zero of the gauge and then, the zero of the controller.

4.2.1 <ZERO> Adjustment

n

Evacuate the gauge to a pressure according to the table below.

	Recommended final pressure for		
F.S.	zero adjustment		
1000 Torr/mbar	<5×10 ⁻² Torr	<6.65×10 ⁰ Pa	<5×10 ⁻² mbar
100 Torr/mbar	<5×10 ⁻³ Torr	<6.65×10 ⁻¹ Pa	<5×10 ⁻³ mbar
10 Torr/mbar	<5×10 ⁻⁴ Torr	<6.65×10 ⁻² Pa	<5×10 ⁻⁴ mbar
1 Torr/mbar	<5×10 ⁻⁵ Torr	<6.65×10 ⁻³ Pa	<5×10 ⁻⁵ mbar


If the final pressure in the gauge is too high for zero adiustment (>25% of the F.S.), the zero cannot be reached and the <RUN> LED flashes. If this is the case, activate the factory setting and adjust the zero again ($\rightarrow \equiv 31$).



Operate the gauge for at least ¼ hour (until the signal is stable).



Briefly press the <ZERO> button with a pin (max. ø1.1 mm). The zero adjustment runs automatically. The <RUN> LED flashes until the adjustment (duration ≤8 s) is completed.





After zero adjustment the gauge automatically returns to measurement mode. The <RUN> I FD lits



The zero can also be adjusted via the RS232C interface $(\rightarrow \square [2]).$

The < RUN> LED flashes if

- the signal output is negative (< -20 mV) when the final pres- sure has been attained
- the zero adjustment has failed.

422 <ZERO> Adjustment with Ramp Function

The ramp function allows to adjust the zero at a known reference pressure within the measurement range of the gauge.

It also permits to adjust an offset of the characteristic curve in order to

- · compensate for the offset of the measuring system or
- obtain a slightly positive zero for a 0 ... 10 V AD converter.

The offset should not exceed 2% of the F.S. (+200 mV). At a higher positive offset, the upper limit of the measurement range is exceeded




Recommended procedure for adjusting the offset of a measuring system: \rightarrow Notice \cong 24.



Operate the gauge for at least ¼ hour (until the signal is stable).



Push the <ZERO> button with a pin (max. ø1.1 mm) and keep it depressed. The <RUN> LED starts flashing. After 5 s. the zero adjustment value, starting at the current output value, keeps continually changing (ramp) until the button is released or until the setting limit (max. 25% F.S.) is reached. The corresponding output signal is delayed by about 1 s.





B Push the <ZERO> button again:

Fine adjustment within 03 s:	the zero adjustment value changes by one unit (push <zero> button in intervals of 1 s)</zero>
Change of direction within 35 s:	the zero adjustment changes its direction (the flashing frequency of the <run> LED changes briefly)</run>



If the <ZERO> button is released for more than 5 s, the gauge returns to the measurement mode.



The zero with Base-Pressure-Offset can also be adjusted via the RS232C interface ($\rightarrow \square$ [2]).

The <RUN> LED flashes if the signal output is negative.


4.3 Switching Functions

The two switching functions can be adjusted to any pressure within the whole measurement range ($\rightarrow B$ 17).

The current setpoint setting

- is output at the D-Sub connector instead of the measurement signal (→
 ^B 22) and can be measured with a voltmeter after the <SP> button is pressed, or
- can be read/written via the RS232C interface.

If the pressure is lower than the setpoint, the corresponding LED is lit (<1> or <2>) and the corresponding relay ($\rightarrow \textcircled{B}$ 22) is energized.



4.3.1 Adjusting the Setpoints

The setpoints can be adjusted via

- the buttons on the gauge,
- the RS232C interface (→ □ [2]).

Λ	
П	<u>۱</u>
÷	

DANGER

DANGER: malfunction


If processes are controlled via the signal output, keep in mind that by pushing the <SP> button the measurement signal is suppressed and the corresponding threshold value is output instead. This can cause malfunctions.

Push the <SP> button only if you are sure that no damages can arise from a malfunction.

Adjusting Setpoint <1>




Push the <SP> button with a pin (max. ø1.1 mm). The gauge changes to the switching function mode and outputs the current lower threshold value at the measurement value output for about 10 s (LED <1> flashes).





2 For changing the threshold value, push the <ZERO> button and keep it depressed. The threshold keeps changing from the current value (ramp) until the button is released or until the limit of the setting range is reached.





B Push the <ZERO> button again:

Fine adjustment within 03 s:	the zero adjustment value changes by one unit
Change of direction within 35 s:	the zero adjustment changes its direction (the flashing frequency of the <run> LED changes briefly)</run>



If the <ZERO> button is released for more than 5 s, the gauge returns the measurement mode.

The upper threshold is automatically set 1% F.S. above the lower one (hysteresis).

Adjusting Setpoint <2>

Push the <SP> button twice (LED <2> flashes). The adjustment procedure is the same as for setpoint <1>.

4.4 Activating the Factory Setting (Factory Reset)

All user defined parameters (e.g. zero, filter) are restored to their default values.



Loading of the default parameters is irreversible.

Loading the default parameters:



• Put the gauge out of operation.



Keep the <ZERO> button depressed for at least 5 s while the gauge is being put into operation (Power ON).

P

5

Deinstallation

WARNING: fragile components

The ceramic sensor may be damaged by impacts. Do not drop the product and prevent shocks and impacts.

STOP DANGER



DANGER: contaminated parts Contaminated parts can be detrimental to health and environment.

Before beginning to work, find out whether any parts are contaminated. Adhere to the relevant regulations and take the necessary precautions when handling contaminated parts.



Caution: vacuum component

Dirt and damages impair the function of the vacuum component.

When handling vacuum components, take appropriate measures to ensure cleanliness and prevent damages.



Caution

Caution: dirt sensitive area

Touching the product or parts thereof with bare hands increases the desorption rate.

Always wear clean, lint-free gloves and use clean tools when working in this area.



• Vent the vacuum system.



2 Put the gauge out off operation.



B Unfasten the lock screws and disconnect the sensor cable.

4 Remove the gauge from the vacuum system and install the protective lid.

6 Maintenance, Repair

Under clean operating conditions, the product requires no maintenance.



Gauge failures due to contamination or wear and tear are not covered by the warranty.

We recommend checking the zero at regular intervals $(\rightarrow \textcircled{B} 25)$.

Agilent assumes no liability and the warranty becomes null and void if any repair work is carried out by the end-user or third parties.

7 Returning the Product

D7	WARNING: forwarding contaminated products
	Contaminated products (e.g. radioactive, toxic, caustic or microbiological hazard) can be detrimental to health and environment.
	Products returned to Agilent should preferably be free of harmful substances. Adhere to the forward- ing regulations of all involved countries and for- warding companies and enclose a duly completed declaration of contamination.

Products that are not clearly declared as "free of harmful substances" are decontaminated at the expense of the customer.

Products not accompanied by a duly completed declaration of contamination are returned to the sender at his own expense.


8 Disposal

OP DANGER

DANGER: contaminated parts

Contaminated parts can be detrimental to health and environment.

Before beginning to work, find out whether any parts are contaminated. Adhere to the relevant regulations and take the necessary precautions when handling contaminated parts.



relevant local regulations.

Separating the components

After disassembling the product, separate its components according to the following criteria:

· Contaminated components

Contaminated components (radioactive, toxic, caustic or biological hazard etc.) must be decontaminated in accordance with the relevant national regulations, separated according to their materials, and disposed of.

· Other components

Such components must be separated according to their materials and recycled.

Further Information

- [1] www.agilent.com Operating Manual AGC-100 Vacuum Gauge Controller tqnb15e1 Agilent Technologies, Lexington, MA 02421, USA
- [2] www.agilent.com Communication Protocol RS232C Interface tqra76e1 Agilent Technologies, Lexington, MA 02421, USA

ETL Certification



ETL LISTED

The product CDG-500 complies with the requirements of the following Standards: UL 61010-1, Issued: 2004/07/12 Ed: 2 Rev: 2005/07/22 CAN/CSA C22.2#61010-1, Issued: 2004/07/12

Notes

Vacuum Products Division Instructions for returning products

Dear Customer:

a > b

Please follow these instructions whenever one of our products needs to be returned.

- Complete the attached Request for Return form and send it to Agilent Technologies (see below), taking particular care to identify all products that have pumped or been exposed to any toxic or hazardous materials.
- After evaluating the information, Agilent Technologies will provide you with a Return Authorization (RA) number via email or fax, as requested.

Note: Depending on the type of return, a Purchase Order may be required at the time the Request for Return is submitted. We will quote any necessary services (evaluation, repair, special cleaning, eg).

- 3) Important steps for the shipment of returning product:
 - · Remove all accessories from the core product (e.g. inlet screens, vent valves).
 - · Prior to shipment, drain any oils or other liquids, purge or flush all gasses, and wipe off any excess residue.
 - If ordering an Advance Exchange product, please use the packaging from the Advance Exchange to return the detective
 product.
 - Seal the product in a plastic bag, and package product carefully to avoid damage in transit. You are responsible for loss or damage in transit.
 - Agilent Technologies is not responsible for returning customer provided packaging or containers.
 - Clearly label partage with RA number. Using the shipping label provided will ensure the proper address and RA number are on the package. Packages shipped to Agilent without a RA clearly written on the outside cannot be accepted and will be returned.
- 4) Return only products for which the RA was issued.
- 5) Product being returned under a RA must be received within 15 business days.
- 6) Ship to the location specified on the printable label, which will be sent, along with the RA number, as soon as we have received all of the required information. Customer is responsible for freight charges on returning product.
- 7) Return shipments must comply with all applicable Shipping Regulations (IATA, DOT, etc.) and carrier requirements.

RETURN THE COMPLETED REQUEST FOR RETURN FORM TO YOUR NEAREST LOCATION:

EUROPE:	NORTH AMERICA:	PACIFIC RIM:
Fax: 00 39 011 9979 330		
Fax Free: 00 800 345 345 00	Fax: 1 781 860 9252	please visit our website for individual
Toll Free: 00 800 234 234 00	Toll Free: 800 882 7426, Option 3	office information
vpt-customercare@agilent.com	vpl-ra@agilent.com	http://www.agilent.com



Vacuum Products Division Request for Return Form (Health and Safety Certification)

Please read important policy information on Page 3 that applies to all returns.

1) CUSTOMER INFORMATION

Company Name:		Contact Name:
Tel:	Email:	Fax
Customer Ship To:		Customer Bill To:
Europe only: VAT reg. Num	nber:	USA/Canada only: Taxable Non-taxable

2) PRODUCT IDENTIFICATION

Product Description	Agilent P/N	Agilent S/N	Original Purchasing Reference

3) TYPE OF RETURN (Choose one from each row and supply Purchase Order if requesting a billable service)

3A	Non-Billable	Billable -	New PO # (hard coov must be submitted with this form	d,

3B.	Exchange	Repair	Upgrade	Consignment/Demo	Calibration	Evaluation	Return for Credit
-----	----------	--------	---------	------------------	-------------	------------	-------------------

4) HEALTH and SAFETY CERTIFICATION

RADIOACTIVE	INOLOGIES CANNO MATERIAL, OR ME echnologies to disc	RCURY AT ITS F	ACILITY.			PLOSIVE HAZARDS,		
The equipmen	HAS pumped or b	d or been exposed been exposed to t		r hazardous mater	ials. If this box is c	hecked, the following ed or was exposed:		
Toxic	Corrosive	Reactive	Flammable	Explosive	Biological	Radioactive		
List all toxic/	List all toxic/hazardous materials. Include product name, chemical name, and chemical symbol or formula:							
NOTE If a product is recoived at Aginet which is contaminated with a twice or hazardous material that was not disclosed, the contamerwell be haid negoesable for all costs income to essure the sub handling of the product, and is liable for any harm or injury to Aginet employees as well as to any third party occurring as a result of exposure to this do handling on the product.								
Print Name:			zed Signature:		Date:			
) FAILURE INFO	RMATION:							
Failure Mode	REQUIRED FIELD.	See next page for	suggestions of fail	are terms):				
Detailed Desc	ription of Malfunctio	on: (Please provid	e the error messao	el				
	stem and model):							
Application (s								
	nd agree to the terr	ms of Section 6, F	Page 3/3.					
			Page 3/3. zed Signature:		Date:			



🔶 Agilent Technologies

Vacuum Products Division Request for Return Form (Health and Safety Certification)

Please use these Failure Mode to describe the concern about the product on Page 2.

	TURBO PUN	PS an	d TURBO CO	NTROLLERS	
APPARENT DEFECT/MALFUNCTION			ITION	PARAMETERS	
- Does not start	- Noise	- Ver	tical	Power:	Rotational Speed:
- Does not spin freely	 Vibrations 	-Hori	contal	Current:	Inlet Pressure:
- Does not reach full speed	-Leak	-Ups	ide-down	Temp 1:	Foreline Pressure:
 Mochanical Contact 	-Overtemperature	-Oth	36	Temp 2:	Purge flow:
Cooling defective Clogging			OPERATING TIME:		IE:
10N	PUMPS/CONTROLLERS			VALVES/CO	OMPONENTS
- Bad feedthrough	Poor vacuum		- Mai	n seal leak	Bellows leak
Vacuum leak - High voltage problem		- Solenoid failure		noid failure	- Damaged flange
Error code on display Other			- Damaged sealing area		-Other
	LEAK DETECTORS			INSTR	JMENTS
Cannot calibrate	-No zero/high backround		- Gau	go tube not working	- Display problem
 Vacuum system unstable 	- Cannot reach test modo		- Com	Communication failure Degas not working	
- Failed to start	- Other		- Erro	r code on display	- Other
SCROLL AND ROTARY	VANE PUMPS			DIFFUSION PUMP	S .
Pump doesn't start	- Noisy pump (describe)		- Hos	ter failure	Electrical problem
- Doesn't reach vacuum	- Over temperature		- Doo	sn't reach vacuum	- Cooling coil damage
- Pump seized	- Other		- Vac	uum leak	- Other

Section 6) ADDITIONAL TERMS

Please read the terms and conditions below as they apply to all returns and are in addition to the Agilent Technologies Vacuum Product Division – Products and Services Terms of Sale.

- Customer is responsible for the freight charges for the returning product. Return shipments must comply with all
 applicable Shipping Regulations (IATA, DOT, etc.) and carrier requirements.
- Dustomers receiving an Advance Exchange product agree to return the defective, rebuildable part to Agilient Technologies
 within 15 business days. Failure to do so, or returning a non-rebuildable part (crashed), will result in an invoice for the
 non-returned/non-rebuildable part.
- Returns for credit toward the purchase of new or refurbished Products are subject to prior Agilent approval and may incur
 a restocking fee. Please reference the original purchase order number.
- Units returned for evaluation will be evaluated, and a quote for repair will be issued. If you choose to have the unit repaired, the cost of the evaluation will be deducted from the final repair pricing. A Purchase Order for the final repair price should be issued within 3 weeks of quotation date. Units without a Purchase Order for repair will be returned to the customer, and the evaluation fee will be invoiced.
- A Special Cleaning fee will apply to all exposed products per Section 4 of this document.
- If requesting a calibration service, units must be functionally capable of being calibrated.

Service & Support

North America Agilent Technologies 121 Hantwell Avenue Lexington, MA 02421 USA Tel:+1781 861 7200 Toll-Free:+1 800 882 7426 Fac:+1781 860 5437 vol-custom essenioeitagilent.com

Benelux Aglent Technologies Netherlands B.V. Herculesweg 8 4338 PL Middelburg: The Netherlands Tel: +31 118 671570 Fax: +31 118 671569 Joil free: 00 800 234 234 00

China

Aglent Technologies (China) Co. Ltd No.3, Wang Jing Bei Lu, Chao Yang District, Beijing, 100102 China Nei: +86 (10) 6439 7888 Fax: +86 (10) 6439 1318 Yoll -Free: 800 820 8266 Yop-customeren(xe@sgliest.com

France

Agilent Technologies France 7 avenue des Tropiques Z.A. de Courtabeeuf – B.P. 12 91941 Leu Wills codex France Tel.: +33 (0) 1 69 86 38 84 Fax: +33 (0) 1 69 86 29 88 Joil free: 00 800 234 234 00 01,sales/#gglest.com

Germany & Austria Aglent Technologies Lyoner Str. 20 60 528 Frankfurt am Main Germany Teil: +49 69 6773 43 2230 Fax: +49 69 6773 43 2250 Tollfner: 00 800 234 234 00

This information is subject to change without notice.

© Agilert Technologies, Inc., 2011 Published in USA, October, 2011

India

Agilent Technologies India Prt. Ltd. GO1. Prime corporate Park, 230) 231, Sahar Road, Opp. Blue Dart Centre, Ancher (East), Mumbal – 400 099 India Bit + 91 22 30648257 Fat: +91 22 30648250 Tai: Holdia/gettect.com

Italy

 Agilent Technologies Italia S.p.A.

 via F.BI Varian 54

 10040 Leini, (brino) Italy

 Pic: = 39 011 997 9310

 Fax: = 39 011 997 9350

 Tell-Free: 00 800 234 234 00

 vpt_aslefikagiteent.com

 vpt_aslefikagiteent.com

Japan

Aglient liechnologies Japan, Ltd. 8th Floor Sumitomo Shibaura Building 4-16-36 Shibaura Minato-ku lokyo 108-0023 Japan Tel:-841 35232 1253 Toll-Free: 0120 655 040 Fax:-813 5232 1710 upi-customerswinceWaglient.com

Когеа

Aglent Technologies Kores Ltd. Shims 2nd Bidg. 2F 966-5 Daechi-dong Kangsam-gu, Seoul Korea 135-280 Tel.: +82 2 3452 2455 Tell-Free: 080 222 2452 Fax: +82 2 3452 2451 usk-customerekeeBaglent.com

Singapore

Aglient Richnologies Singapore Pte Ltd No.1 Yishun Avenue 7 Singapore 768923 Tel: +65 6215 8045 Fax: +65 6754 0574 Ioll-Free: 1 800 2762622 upis-customereerice/Raglient.com South East Asia Agleni Technolytes Sales Sin Bhd Unit 201, Level 2 uptom 2, 2 Jalan 5521/37, Damaniara Uptom 47400 Petaling Jaya, Selanger, Malayai Bei - 603 7712 6106 Fax: =603 6733 8121 Toil-Free: 1 800 880 805 typ-cutomesence/ellegilent.com

Taiwan Aglent Technologies Taiwan Limited 20 Kao-Shuang Rd., Pin-Chen City, 324 Taojuan Hsien, Taiwan, R.O.C. Tel. + 866 34959281 Toil Free: 0800 051 342 tyw-customersenice@aglent.com

UK & Ire band Agilent Technologies UKLtd 6 Mead Road Onford Industrial Park Yamton, Oxford 0X5 1QU UK Tel: +44 (0) 1865 291570 Fax: +44 (0) 1865 291571 Toil tes: 00 800 234 234 00 vpt-customerseviceil agilent.com

Learn more: www.aglent.com/chem/vacuum

Agilent Technologies

BROOK

