

## HPS® 910 DualTrans MicroPirani/Absolute Piezo Transducer


Pin	Description
1	RS485 (-) / 232 transmit
2	RS485 (+) / 232 receive
3	Power (+)
4	Power (-)
5	Analog Output (+)
6	Analog Output (-)
7	Relay #1 NO
8	Relay #1 Common
9	Relay #1 NC
10	Relay #2 NC
11	Relay #2 Common
12	Relay #2 NO
13	Relay #3 NC
14	Relay #3 Common
15	Relay #3 NO

---

### Note:

This information is subject to change without notice.

---



### Need help?

Contact MKS Instruments by [sending an email to MKS](#) or call **800-227-8766** or **978-645-5500** (outside the USA).